

UPDATE 2007	Previous NAME	Facility Name	Ref. ID	Description	Eligible status	RIVER	MANAGING AGENCY	LENGTH	HEIGHT	WIDTH	LOP	FREEBRD	Material	Internal Drainage	SURVEY DATA	MAINT SCHED	REPAIR AND REHABILITATION	
FEDERAL RIGHT BANK UPPER	NA 2	Gordon Lake Levee	FED-RB1	Gordon Lake Levee, BN RR Levee to I-82	Federal Authorized	Naches	YCPs	1593	8-12	12	100	3		Flood control gate under Hwy 12	County Nov 1993, Consultant Jan. 2007	Semi-annual	None noted	
FEDERAL RIGHT BANK UPPER	Y10		FED-RB2	From I-82/Naches Confluence to I-82 at Cascade Lumber.	Federal	Yakima	YCPs	5700	8-15	12	100	3		24" CMP culvert, 500' d/s of Hwy 82. 36"x48" twin conc culvert, Cascade Lumber headworks, 1800' d/s of Hwy 82. 24" CMP culvert, 3400' d/s of Hwy 82.	County Jul 1994 survey; County Mar 1994 survey and 2000 LiDAR		Remove 1500 of Levee near	
FEDERAL RIGHT BANK LOWER		FEDRB3	FED-RB3	I-82 at Cascade Lumber Co to Terrace Hts Drive	Federal	Yakima	YCPs	7000	6-12	12	100	3		Wooden outlet works of Cascade Lumber, 1800' u/s of NPPR Moxee Branch line. 36" twin CMP culvert w/circular auto gate, 1650' d/s of NPPR Moxee Branch line. 36" twin CMP culvert w/circular auto.	County 1988 survey 2000 LiDAR	Semi-annual	Portion removed and tied into I-82 by City of Yakima to Federal 100 yr standards in 1998.	
FEDERAL RIGHT BANK LOWER	Y10		FED-RB4	From Terrace Heights Drive to SR 24, West Bank	Federal	Yakima	YCPs	8500	0-18	12	100	3		36" CMP culvert w/circular auto drainage gate, 3100' u/s from Old Moxee Hwy. 6" CMP culvert, 950' u/s from Old Moxee Hwy. 36" CMP culvert w/circular auto drainage.	Yakima County and 2000 LiDAR	Semi-annual	None noted	
Marsh Road	Lower Portion of Y9	FED-LB1	FED-LB1	NPPR Branch Line to East bank Yakima River,	Federal	Yakima	YCPs	2000	5-10	9-15	100	3	Silty sand gravel to sandy gravel	Moxee irrigation canal 48"x72" RCP culvert at u/s end of Wasteway #2 dike, 2 - 36"x48" hand operated lift gates. Union Gap irrigation canal 36"x48" RCP culvert, 800' from u/s end of Wasteway #2 dike, 1 - 36"x48" hand operated lift gates.	Yakima County 2000 LiDAR	Semi-annual	1972 - 1200 LF riprapped; 1974 - 150 LF riprapped. 1977 - 950 LF riprapped & rehabilitated. 1983 - 640 LF riprapped.	
FEDERAL LEFT BANK LEVEE		FEDLB2	FED-LB2	From Selah Moxee Canal, along NPPR Moxee Branch Line to WW No 2 RB Levee	Federal	Yakima	YCPs	2100		12	100	3		1 - 36" RCP culvert thru NPPR embankment, 350' east of trestle.	County May 1992 survey	Semi-annual	Not available	
FEDERAL LEFT BANK LEVEE	Y-8 East	Roza Wasteway #2 East Bank	FED-LB3	East Bank Wasteway #2 Levee from Terrace Heights Dr. to NPPR	Federal	Yakima	BOR	3400	5-12	10	100			Richartz ditch crossing, 36" RCP culvert under wasteway dike fitted w/hand-operated lift gate, 400' d/s from NPPR.	County June 1993 survey	Semi-annual	YCPs raised elevation in 1993	
FEDERAL LEFT BANK LEVEE	Y7A	Dike South of Terrace Height Drive	FED-LB4	KOA Levee, From Terrace Heights Dr. TO Old Moxee Brg. (Birchfield Rd).	Federal	Yakima	YCPs	9300	3-13		12	100	3			County Oct 1992 survey	Semi-annual	YCPs relocated and raised in 1995.
FEDERAL LEFT BANK LEVEE	YSEG7A	KOA Levee	YSEG7A	Old Moxee Bridge (Birchfield Rd) to SR 24 Bridge, Lft Bank	Federal	Yakima	YCPs	1670	3-12	12	5	1	Predominantly clean to silty gravel		COE Dec 1991 survey Diking District #1	Annual	1972 - 2375 LF restored. 1974 - 1000 LF repaired and restored. Updated by YCPs to federal status 1995.	
BOR-W	Y-8 West	Roza Wasteway #2 West Bank BOR	BOR-W (OLD) FED-LB3	Wasteway #2 Levee from Terrace Heights Dr. to NPPR	Unknown	Yakima	BOR	2900	5-12	10	unknown			Richartz ditch crossing, 36" RCP culvert under wasteway dike fitted w/hand-operated lift gate, 400' d/s from NPPR.	County June 1993 survey	Semi-annual	Not available	
WWTP	Y-8	Yakima Regional WWTP Levee	PL99-YSEG8	Downstream SR 24, protects city wwtp	PL-84-99	Yakima	City of Yakima	5477	3-5	10-25	5	1	Silty sandy gravel	One pumphouse	COE	Annual	1969 - 700 LF was reinforced. 1974 - 400 LF riprapped and reshaped. 1976 - 175 LF riprapped. 1978 - 530 LF rehabilitated and riprapped. 1982 - 500 LF rehabilitated and riprapped.	
	Y1		YSEG1	West Bank Downstream of Zillah	Non-certified	Yakima	Yakama Nation	4450	5-10	12-15	10	3	Silty sandy gravel	One ungated culvert at station 15+50	Not available - verify with COE	Unknown	1978 - 1415 LF rehabilitated and riprapped by COE	
Yakama Nation	Y2A		PL99-YSEG2A	West Bank Levee upstream of SR-22	PL-84-99	Yakima	Yakama Nation	11450	3-10	10-18	5	1	Silty sand and silty sandy gravel	Ungated 18" culvert at station 10+50. Drainage ditch along side of the levee.	COE	Annual		
	Y2B		YSEG5	Downstream of Donald Wapato, West Bank	Non-certified	Yakima	Yakama Nation	7300	3-5	10-15	5	1	Silty sandy gravel with cobbles	1 - 12" ungated culvert	COE	Unknown	This levee segment failed to meet minimum PL-99 criteria during initial inspection due to ungated culvert and unmaintained overgrowth.	
	YSEG2B		YSEG2B	Old No. 53	Non-certified	Yakima	Yakama Nation	3745	3-4	8-10	5	1	Silty sand, sandy silt, silty gravel	None provided	Not available - verify with COE	Unknown	1972 - 400 LF cross dike construction & 2225 LF restored by COE	
	Y3	Donald Bridge Levee	YSEG3	At Donald Wapato Br. Protects center abutment of	Non-certified	Yakima	YCPs	720	4-8	12-14	5	1	Predominately sandy gravel with silt	None provided	Not available - verify with COE	None	1978 - 550 LF was rehabilitated & riprapped by COE.	
Wapato Bridge	Y4	Donald Bridge Levee	YSEG4	Protects Wrecking Yard, Eastern abutment of west s	Certified	Yakima	YCPs	400	3	10	5	1	Silty sandy gravel	None provided	Not available - verify with COE	None	1978 - 200 LF were riprapped by COE	
	Y4		YSEG6	Downstream of Wapato Diversion, protects Parker	Non-certified	Yakima	YCPs	3600	3-10	10-15	5	1	Predominately silty sandy gravel with cobbles	Underground irrigation ditch drainage culvert	COE	None	1978 - 750 LF restored and riprapped.	
Diking District # 1	Y7B	Levee d/s of Hwy 24	YSEG7	From SR 24 to Bell Road, East Bank	Non-certified	Yakima	Diking District No. 1	9396	3-12	8-20	5	1	Predominately clean to silty gravel	6" pump in gravel pit. 20" culvert with silted intake structure.	COE, Diking District No. 1	None	1972 - 2375 LF restored. 1974 - 1000 LF repaired and restored.	
Selah Gravel Pit	YSEG10	East Selah Gravel Pit	YSEG10	Protects gravel ponds near Selah	Non-certified	Yakima	Private								Phase 1 Report, East Selah Regulating Reservoir (CH2M Hill, 1984)	Unknown		
Rambler's Park Levee	Naches 1	Rambler Park / Weber Auto Wrecking Dike	PL99-NSEG1	Ramblers Park Levee	PL-84-99	Naches	YCPs	2336	3-7	10-15	10	3	Clean to slightly silty sand & gravels	None provided	Available from COE	Annual	1972 - 300 LF riprapped by COE. 1974 - 200 LF rock replacement by COE. 1976 - 250 LF riprapped by COE. 1977 - 175 LF reconstructed. 1996 - reconstructed.	
McCormick Levee	Naches 2	McCormick Dike	PL99-NSEG2	McCormick Levee	PL-84-99	Naches	YCPs	2378	3-7	10-12	5	1	Clean to slightly silty sandy gravel with cobbles	None provided	Not available - verify with COE	Annual	1973 - 900 LF repaired. 1974 - 650 LF reconstructed and rock protection. 1978 - 280 LF rehabilitated.	
	Naches 4		NSEG4	HWY 12 Downsteam of Yakima WTP	Non-certified	Naches	YCPs	800	3	4-6	10	3	Silty sandy gravel	None provided	Not available - verify with COE	None	1974 - 600 LF reshaped and rock protection. 1974 - 250 LF rock protection.	
Eschback	Naches 5		NSEG5	Protects Canal and Eschbach Pk.	Other	Naches	YCPs	1655	3-8	0-25	5	1	Sandy gravel	None provided	Not available - verify with COE	None	1974 - 600 LF reshaped and armored by COE.	
WTP	Naches 6		PL99-NSEG6	Protects City WTP	PL-84-99	Naches	City of Yakima	1152	4-8	10-11	5	1	Sandy gravel with cobbles	None provided	Not available - verify with COE	Annual	1973 - 450 LF repaired	
Town of Naches	Naches 7	Naches Dike	PL99-NSEG7	Protects town of Naches and N. Abut S. Naches Rd.	PL-84-99	Naches	YCPs	5885	3-10	12-17	5	1	Clean to slightly silty sandy gravel with cobbles	1 - 48" ungated culvert at station 59+00. 1-24" ungated culvert at station 59+50	Not available - verify with COE	Annual	1976 - 350 LF riprapped, 2360 LF reconstructed by COE. 1981 - 1000 LF restored.	
Naches Right	Naches 8	Naches Dike	PL99-NSEG8	Protects S Bridge Abutment, S. Naches Rd.	PL-84-99	Naches	YCPs	1688	3-6	8-15	5	1	Clean gravels and cobbles	None provided	COE	Annual	1978 - 1400 LF rehabilitation.	
South Naches	Naches 9	Naches Dike South Side	PL99-NSEG9	Corps Levee protecting S. Naches Ditch and Craig	PL-84-99	Naches	YCPs	2100	3-5	12-20	5	1	Sandy gravel with cobbles and quarry spoils	None provided through the embankment, although the irrigation ditch drains to landward of the levee	Not available - verify with COE	Annual	1965 - 1850 LF riprap protection and irrigation canal protection. 1974 - 200 LF riprapped, 1000 LF rehabilitation.	
	NSEG10		NSEG10	Segment No. 10 Naches	Non-certified	Naches	YCPs	693	3-5	10-12			Silty sandy gravel with cobbles	None provided through the embankment, although an irrigation ditch drains landward of the levee	Not available - verify with COE	None	1978 - 515 LF rehabilitated in 1978 by COE.	
Rock Creek	Naches 11		NSEG11	Vicinity of Rock Creek	Other	Naches	YCPs	2140	4-5	8-12	5	1	Silty sandy gravel with cobbles	None provided through the embankment, although drainage may pass into Rock Creek downstream	Not available - verify with COE	None	1975 - 550 LF restored and riprapped. 1978 - 900 LF rehabilitated.	
	Cliffdell Br.		NSEG12	Downstream of Cliffdell Br.	Non-certified	Naches	YCPs	400	3-6	25	5	1	Silty sandy gravel	Gated culvert at u/s end	Not available - verify with COE	None	1978 - 400 LF rehabilitated	