



CROSS SECTION  
NTS

NOTES:

- 1) CONNECT TRACER WIRE TO MAINLINE TRACER WIRE WITH WATER TIGHT CONNECTOR AND TO BLOW OFF WITH NYLON ZIP-TIES. TAPE TO PE PIPE AT 6' INTERVALS.

BLOW OFF ASSEMBLY



APPROVED BY:

*Joe Sturz*  
Utilities Manager

1/8/15

DATE:

REVISION:

K.P.

J.M.

J.M.

J.M.

DESCRIPTION:

STANDARD REVIEW

STANDARD REVIEW

ADDED TRACER WIRE AND ZIP-TIE INFO.

REVISED NOTE: WATER TIGHT

DATE:

02-28-03

06-09-09

3-11-11

12-12-14

STANDARD PLAN

W-2

SHEET 1 OF 1

FILE NAME: G:\STANDARDS\WATER\W2.DWG