

Wide Hollow Creek 72nd – 80th Conveyance Project
Winter 2009-2010

Project Area



Large woody debris created from collapsing hybrid willows and beaver dams have drastically reduced conveyance of Wide Hollow Creek. Due to these conditions, the creek would leave its banks and produce minor flooding problems during normal water flows.



Scope of Work

Remove the woody debris and beaver dams from the creek's channel. Remove woody debris less than 8 inches in diameter off site, leave the larger woody debris on site. Remove two foot bridges, straighten the channel in two locations and re-vegetate the disturbed areas and areas void of vegetation.





Beaver Dam

Before



After



Before



After



Beaver Dam

Before



After

New
main
channel



Original
channel,
now a
bypass
channel

Original
channel



Additional
channel